

Zap- Ox Application Instructions

Zap-Ox is a unique cream cleanser for completely removing oxidation in the form of rust, gas stains, and other hard to remove residue. The following are instructions of how to use Zap-Ox. There are two different ways to use Zap Ox: Scrubbing or Without Scrubbing. Scrubbing is generally not necessary for most stains. Scrubbing is only used where residue is thick or baked on.

Without Scrubbing

- Rub a thin layer of Zap-Ox to the surface
- Let it sit for 5-10 minutes depending on the severity of the stain. Wipe away with rag/cloth, cleaner, or water. (Zap-Ox is non caustic, so it will not attack the surface after applying)
- If stain is not removed apply another layer of Zap-Ox and extend the time before wiping.

Scrubbing

- Apply a thin layer of Zap-Ox to the surface
- Scrub in the layer of Zap-ox until the rust or gas staining is removed. Wipe away with rag/cloth, cleaner, or water. (Zap-Ox is non caustic, so it will not attack the surface after applying)
- Zap-Ox does have a small amount of Silica (synthetic sand), so rub gently if worried about scratching the surface.

Applying Zap Ox to Textured Surface (At Customers Own Risk)

- Apply a thin layer of Zap-Ox to the textured surface.
- Smooth over the surface without rubbing to avoid scratching with the silica. Let Zap-Ox sit for 5- 10 minutes. Wash away (don't wipe) with cleaner or water to avoid scratching the surface with the silica.

Using Zap-Ox on Warm or Hot Surfaces

-When using Zap-Ox on warm or hot surfaces it is important to add a small amount of lubricant to the hot surface before applying the Zap-Ox to avoid drying of the product.